X/o	wlz	Ord	lar l	ID	ፈበር	04
พ ก	rk	ura	ler i	11)	กแร	194

Quality Control



Page 1

August 3, 2010	3:20:32 PM											
Item ID: Revision ID:	D3417-9 PRELIM		11	Accept						_		
Item Name: Start Date: Required Date Reference:	Washer 03/08/2010 : 10/08/2010	5.0 Start Qty: 20.00 Req'd Qty: 20.00	Gr/ 	8 2 1		Cust Item II Customer:) :	(F	OSITIVE ECALL	S	top	
Approvals:	Process Pla	n:	Date:	_ Tooling:		Dat	te:	·	3		1 1881114	
	QC:	AND CONTRACTOR OF THE CONTRACT	Date:	_ SPC (Y/N):		Dat	te:			S	top	
Sequence ID/ Work Center 1	D	Operation Description		Set Up/ Run Hours		Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr D3417	Rev PE	ision Nbr										
		Hardinge CNC LATHE S	SMALL	0.00								
Doosan		Memo	D. 2: 10.004	0.00								
Doosan Lathe		Folio Rev: No. 10 Dwg D3417	er Folio FA954 //A Rev: PF1	-	SL	10/08/6	5	(5			
		2-Deburr						•				
110		QC2- Inspect parts off ma	achine FAI/FAIB	0.00		, (, ,)						
QC		Memo		ح 0.00	ル /	10/08/6S	•		···			

Work Order ID 60994

August 3, 2010 3:20:32 PM



Page 2

Item ID:

D3417-9

PRELIM

Revision ID: Item Name:

Washer

Start Date:

Required Date: 10/08/2010

03/08/2010

Start Qty: 20.00

Req'd Qty: 20.00



Accept



Setup Start



Stop

Reference:

Approvals:

Process Plan:

Operation

Description

Date:_____

Date:_____ Tooling:

SPC (Y/N):

Set Up/

0.00

0.00

Run Hours

Date:

Tool ID

Date:

Tool # Plan

Code

Cust Item ID:

Customer:

Run

Start



Stop

Reject

Qty

Insp.

Stamp

Sequence ID/ Work Center ID

120

Memo

Quality Control

QC8- Inspect parts - second check

Identify as per dwg & Stock Location:

Memo

Memo

0.00

0.00

Accept

Qty

Reject

Number

Packaging

Packaging

140

130

Quality Control

QC21- Final Inspection - Work Order Release

0.00

0.00

POSITIVE RECALL

EFFECTIVE DOWN AUTH

RELEASED

MC 11-03-14

Picklist Print

August 3, 2010 3:20:31 PM

Work Order ID: 60994

Parent Item: D3417-9

Parent Item Name: Washer



Start Date: 03/08/2010

Required Date: 10/08/2010

Page 1


Start Qty: 20.00


Required Qty: 20.00


Comments:

Ipp Rev:A New Issue 10-08-03 JLM Verified By:DD

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
MDELRINR1.2500 DELRIN ROUND BAR 1.2	1111	Purchased	No				f	32.1500	0.0296	0.623158			
				Location	!	Loc	Qtv	Loc Code					
				MAT		3	2.15						
					114586		19.3						,
					114733	1	2.85			.62	-31	10/08	-/







DART AEROSPACE LTD	Work Order:	60994
Description: Washer	Part Number:	D34/2-9
Inspection Dwg: D34/3 Rev: PRI		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
1.125	+ 03	1.141			vern JL	3
1.103 05 (H)	+-008	.642			. 1	
.18)	+.03 +.008 001 +.010	. 179			1 "	
R1.58	030	1.58			(.9	
. 078	± -010	.078			UP(n "	
			<u> </u>			
				-		
				 		
					·	
					<u> </u>	

Measured by:	Audited by:	Preliminary Approval:
Date: 10/88/05	Date: John 10/0	S/s Date:
10/08/07	h. Ond Star 10/14	

Rev	Date	Change	Revised by	Approved
	10.04.14	Added preliminary approval	KJ	

Reinspection Rec P Dry. Sillis/14

\$ 10.04.15

— Ø0.641 **–** Ø1.125 +0.030 V R1.58 D3417-9 WASHER DESIGN DRAWN DART AEROSPACE LTD
HAWKESJURY, ONTARIO, CANADA
DRAWING NO.
D3417 SINCE
WASHER CHECKED MFG. APPR. REV. F SHEET 3 OF 3 APPROVED SCALE DE APPR.

DATE 10.07,26